

Bulletin Number: AKSV0100

Date: 6/7/05

Subject: Proper Stowage of the Power Cord on all AKSV Mobile Products

## Photos



The power cord must be rolled up in a figure 8 to ensure that the wiring internal to the cord does not get twisted and possibly cause a short. Rolling the cable in a circular fashion can cause the wiring to twist inside of the insulation and cause serious damage to the cord and other electrical components. Correct stowage is shown above.